

Trimble® Access™ Aerial Imaging Software

Version 2.2.2
Revision A
July 2016



Legal Information

Trimble Navigation Limited
Engineering Construction Group
935 Stewart Drive
Sunnyvale, California 94085
U.S.A.
www.trimble.com

Copyright and Trademarks

© 2013–2016, Trimble Navigation Limited. All rights reserved.

Trimble and the Globe and Triangle logo are trademarks of Trimble Navigation Limited, registered in the United States and in other countries.

Access is a trademark of Trimble Navigation Limited.

Microsoft, ActiveSync, Windows, and Windows Mobile are either registered trademarks or trademarks of Microsoft Corporation in the United States and/or other countries.

The Bluetooth word mark and logos are owned by the Bluetooth SIG, Inc. and any use of such marks by Trimble Navigation Limited is under license.

All other trademarks are the property of their respective owners.

This document is for informational purposes only. Trimble makes no warranties, expressed or implied, in this document.

Aerial Imaging Software Version 2.2.2

These Release Notes contain information about the Trimble® Access™ Aerial Imaging software version 2.2.2.

This version of Aerial Imaging is backward compatible with projects created in Aerial Imaging version 2.x.x.

Safety improvements

- The firmware now handles low battery voltages more accurately.

New features

- Aerial Imaging version 2.2.2 supports the Sony a6000 camera for the ZX5 aerial imaging rover. The Sony a6000 camera is a 24.3 megapixel camera, and is fitted with the Sony E 16 mm F2.8 pancake lens. For more information, refer to the Trimble ZX5 Aerial Imaging Solution User Guide.

Resolved issues

- An issue where large .gwt files failed to import is now resolved.
- An issue where viewing the flight settings marked the project as changed is now resolved.
- An issue with memory leaks is now resolved.

Documentation updates

In addition to documenting the Sony a6000 camera, the Help files and user guides available for this version of the software include updates to the UX5 HP/UX5 autopilot error messages topic to include error messages 229 through 235.

Installation information

Installing the software and licenses on the GCS

Operating system installation

With a new Trimble Tablet, the operating system is not installed. Turn on the Tablet to install the Windows® operating system and then apply Windows updates. The operating system must be Windows 7.

Software and license installation

Before you use your controller, you must install the applications and licenses using the Trimble Installation Manager. If you have:

- Never installed the Trimble Installation Manager, go to www.trimble.com/installationmanager for installation information.
- Previously installed the Trimble Installation Manager, you do not need to reinstall it because it updates itself automatically. Select *Start / All Programs / Trimble Installation Manager* to start the Installation Manager.

For more information, click *Help* in the Trimble Installation Manager.

Note – *An update of the Aerial Imaging software usually includes an eBox firmware update. The update is triggered during the flight checklist and can take up to 30 minutes.*

Updating office software

When you upgrade to version 2.2.2, you must also update your office software.

When you upgrade the controller using the Trimble Installation Manager, the office software on the computer that has the Trimble Installation Manager installed is also upgraded.

To upgrade other computers that were not used to update the controller, install the Trimble Installation Manager onto each computer and then update the office software.

Documentation

The *Aerial Imaging Help* is "context-sensitive." To access the Help, tap ? at the top of the screen. A list of Help topics appears, with the relevant topic highlighted.